

Exhibit 15

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET****Customer:** Joseph D. Satterley, Esq.**Sample Number:** Gordon Grids**J3 Order #:** JH1895372**Grids:** 1A-1D**High Magnification Scan at 15,000X**

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1A	A1				Damaged				
	A2				Damaged				
	A3				Damaged				
	A4				Damaged				
	A5		1	8.5 x 0.05	Chrysotile	Yes	02,03	01	
	A6				Damaged				
	A7		NSD						
	A8				Damaged				
	A9		NSD						
	A10				Damaged				
	B1		NSD						
	B2				Damaged				
	B3				Damaged				
	B4				Damaged				
	B5				Damaged				
	B6				Damaged				
	B7		2	3 x 0.10	Tremolite	Yes	04	05	Adjacent Grid Bar
	B8		NSD						
	B9		NSD						
	B10				Damaged				
	C1				Damaged				
	C2				Damaged				
	C3				Damaged				
	C4				Damaged				
	C5				Damaged				
	C6				Damaged				
	C7				Damaged				
	C8		NSD						
	C9	✓	NA	11 x 0.60	Talc				Talc Ribbon
	C10	✓	NA	3 x 0.50	Talc				Particle
	D1		NSD						
	D2				Damaged				
	D3				Damaged				
	D4				Damaged				
	D5				Damaged				
	D6		NSD						
	D7		NSD						
	D8		NSD						

Lee Poye Analyst

26-Jan-2018

Date



Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1A	D9		NSD						
	D10				Damaged				
	E1		NSD						
	E2				Damaged				
	E3				Damaged				
	E4		NSD						
	E5				Damaged				
	E6				Damaged				
	E7		NSD						
	E8				Damaged				
	E9				Damaged				
	E10				Damaged				
	F1		NSD						
	F2				Damaged				
	F3		NA	6.5 x 0.60	Talc	Yes	08		Ribbon
	F4		NSD						
	F5				Damaged				
	F6		NA	5 x 3.50	Talc	Yes	09	10	Particle
	F7				Damaged				
	F8				Damaged				
	F9				Damaged				
	F10				Damaged				
	G1				Damaged				
	G2				Damaged				
	G3		NA	5 x 1.00	Talc	Yes	11		Fiber
	G4				Damaged				
	G5				Damaged				
	G6		NSD						
	G7				Damaged				
	G8		NSD						
	G9				Damaged				
	G10				Damaged				
	H1				Damaged				
	H2		3	14.5 x 0.30	Tremolite				RJLG Identified
	H3				Damaged				
	H4				Damaged				
	H5				Damaged				
	H6				Damaged				

Lee Poye

Analyst

26-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1A	H7		NSD						
	H8				Damaged				
	H9				Damaged				
	H10				Damaged				
	I1				Damaged				
	I2				Damaged				
	I3		NSD						
	I4				Damaged				
	I5		NSD						
	I6				Damaged				
	I7		NSD						
	I8				Damaged				
	I9				Damaged				
	I10				Damaged				
	J1				Damaged				
	J2				Damaged				
	J3				Damaged				
	J4				Damaged				
	J5		NSD						
	J6		NSD						
	J7				Damaged				
	J8				Damaged				
	J9		NSD						
	J10		NSD						
1B									
	A1		NSD						
	A2		NSD						
	A3		NSD						
	A4				Damaged				
	A5				Damaged				
	A6		NSD						
	A7		NSD						
	A8		NSD						
	A9		NSD						
	A10		NSD						
	B1		NSD						
	B2	✓	NA	1.4 x 0.36	Anthophyllite	12	13		AR < 5: 1
	B3				Damaged				

Lee Poye

Analyst

26-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1B	B4				Damaged				
	B5				Damaged				
	B6		NSD						
	B7		4	30 x 1.00	Crocidolite	Yes	14		RJLG Identified
	B8		NSD						
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2				Damaged				
	C3				Damaged				
	C4		NSD						
	C5				Damaged				
	C6		NSD						
	C7		NSD						
	C8		NSD						
	C9		NSD						
	C10		NSD						
	D1				Damaged				
	D2				Damaged				
	D3		NSD						
	D4		NSD						
	D5		NSD						
	D6		NSD						
	D7				Damaged				
	D8		NSD						
	D9		NSD						
	D10		NSD						
	E1		NSD						
	E2				Damaged				
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6		NSD						
	E7		NSD						
	E8		NSD						
	E9	✓	NA	11 x 0.60	Talc	Yes			
	E10				Damaged				
	F1		NSD						

 Lee Poye

Analyst

27-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1B	F2				Damaged				
	F3				Damaged				
	F4		NSD						
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9		NSD						
	F10				Damaged				
	G1				Damaged				
	G2		NSD						
	G3		NSD						
	G4		NSD						
	G5		NSD						
	G6		NSD						
	G7		5	2 x 0.40	Tremolite	Yes	15	16	Bundle
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						
	H4		NSD						
	H5		NSD						
	H6		6	3.7 x 0.25	Anthophyllite	Yes	17	18	
	H7		NSD						
	H8		NSD						
	H9		NSD						
	H10		NSD						
	I1		NSD						
	I2		NSD						
	I3	✓	NA	4.5 x 0.90	Unknown	Yes	19		Mg, Al, Si, K, Ca, Fe
	I4		NSD						
	I5				Damaged				
	I6				Damaged				
	I7		NSD						
	I8		NSD						
	I9		NSD						

Lee Poye

Analyst

27-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1B	I10		NSD						
	J1		NSD						
	J2		NSD						
	J3		NSD						
	J4		NSD						
	J5		NSD						
	J6				Damaged				
	J7				Damaged				
	J8		NSD						
	J9		NSD						
	J10		NSD						
1C									
	A1				Damaged				
	A2		NSD						
	A3				Damaged				
	A4				Damaged				
	A5		NSD						
	A6		NSD						
	A7		NSD						
	A8		NSD						
	A9		NSD						
	A10				Damaged				
	B1		NSD						
	B2		NSD						
	B3		NSD						
	B4				Damaged				
	B5		NSD						
	B6		NSD						
	B7		NSD						
	B8				Damaged				
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2		NSD						
	C3		NSD						
	C4		NSD						
	C5		NSD						
	C6		NSD						

A handwritten signature in black ink, appearing to read 'Lee Poye', is written over a horizontal line.

Lee Poye

Analyst

27-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1C	C7		NSD						
	C8		NSD						
	C9		NSD						
	C10		NSD						
	D1				Damaged				
	D2		NSD						
	D3		NSD						
	D4		NSD						
	D5				Damaged				
	D6		NSD						
	D7		NSD						
	D8		NSD						
	D9		NSD						
	D10		NSD						
	E1		NSD						
	E2		7	3 x 0.50	Anthophyllite	Yes	20	22	
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6				Damaged				
	E7		NSD						
	E8				Damaged				
	E9				Damaged				
	E10		NSD						
	F1		NSD						
	F2				Damaged				
	F3		NSD						
	F4		NSD						
	F5		NSD						
	F6				Damaged				
	F7		NSD						
	F8		NSD						
	F9				Damaged				
	F10		NSD						
	G1		8	3.5 x 0.20	Tremolite	Yes	23	24	
	G2		NSD						
	G3		NSD						
	G4		NSD						

Lee Poye

Analyst

27-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET****Customer:** Joseph D. Satterley, Esq.**J3 Order #:** JH1895372**Sample Number:** Gordon Grids**Grids:** 1A-1D**High Magnification Scan at 15,000X**

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1C	G5		9	2 x 0.30	Anthophyllite	Yes	25	26	
	G6		NSD						
	G7		NSD						
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2				Damaged				
	H3		NSD						
	H4		NSD						
	H5		NSD						
	H6		NSD						
	H7		NSD						
	H8		NSD						
	H9		NSD						
	H10		NSD						
	I1				Damaged				
	I2		NSD						
	I3		NSD						
	I4				Damaged				
	I5		NSD						
	I6		NSD						
	I7		NSD						
	I8		NSD						
	I9		NSD						
	I10		NSD						
	J1				Damaged				
	J2		NSD						
	J3				Damaged				
	J4				Damaged				
	J5				Damaged				RJLG Identified
	J6		NSD						
	J7		NSD						
	J8				Damaged				
	J9		NSD						
	J10		NSD						
1D									
	A1		NSD						

Lee Poye

Analyst

27-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

Sample Number: Gordon Grids

J3 Order #: JH1895372

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1D	A2		NSD						
	A3				Damaged				
	A4		NSD						
	A5		NSD						
	A6	✓	NA	3 x 0.40	Tremolite	Yes	27		Cleavage Fragment
	A7		NSD						
	A8		NSD						
	A9		NSD						
	A10		NSD						
	B1		NSD						
	B2		NSD						
	B3				Damaged				
	B4				Damaged				
	B5		NSD						
	B6		NSD						
	B7		NSD						
	B8		NSD						
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2		NSD						
	C3				Damaged				
	C4		NSD						
	C5		NSD						
	C6		NSD						
	C7		NSD						
	C8		NSD						
	C9		NSD						
	C10		NSD						
	D1		NSD						
	D2		NSD						
	D3		NSD						
	D4				Damaged				
	D5		NSD						
	D6		NSD						
	D7		NSD						
	D8				Damaged				
	D9				Damaged				

Lee Poye

Analyst

28-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 1A-1D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
1D	D10				Damaged				
	E1				Damaged				
	E2		NSD						
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6		NSD						
	E7		NSD						
	E8		NSD						
	E9				Damaged				
	E10				Damaged				
	F1				Damaged				
	F2		NSD						
	F3		NSD						
	F4				Damaged				
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9				Damaged				
	F10		NSD						
	G1		NSD						
	G2		NSD						
	G3		NSD						
	G4		NSD						
	G5				Damaged				
	G6		NSD						
	G7		NSD						
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						
	H4		NSD						
	H5		NSD						
	H6		NSD						
	H7		NSD						

Lee Poye

Analyst

28-Jan-2018

Date

Date _____

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.
J3 Order #: JH1895372

Sample Number: Gordon Grids
Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2A	A1		NSD						
	A2		NSD						
	A3		NSD						
	A4		NSD						
	A5								
	A6				Damaged				
	A7				Damaged				
	A8				Damaged				
	A9		NSD						
	A10		NSD						
	B1								
	B2				Damaged				
	B3				Damaged				
	B4				Damaged				
	B5				Damaged				
	B6				Damaged				
	B7		NSD						
	B8		NSD						
	B9				Damaged				
	B10				Damaged				
	C1		NSD						
	C2		NSD						
	C3								
	C4		NSD		Damaged				
	C5		NSD						
	C6		NSD						
	C7								
	C8				Damaged				
	C9				Damaged				
	C10				Damaged				
	D1		NSD						
	D2		NSD						
	D3		NSD						
	D4		NSD						
	D5		NSD						
	D6		NSD						
	D7		NSD						
	D8		NSD						

Lee Poye

Analyst

29-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case

LAB WORKSHEET



Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2A	D9		NSD						
	D10				Damaged				
	E1		NSD						
	E2		NSD						
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6		NSD						
	E7		NSD						
	E8		NSD						
	E9		NSD						
	E10		NSD						
	F1		NSD						
	F2		NSD						
	F3		NSD						
	F4		NSD						
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9				Damaged				
	F10		NSD						
	G1		NSD						
	G2				Damaged				
	G3		NSD						
	G4		NSD						
	G5		NSD						
	G6		NSD						
	G7				Damaged				
	G8				Damaged				
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						
	H4		NSD						
	H5	✓	NA	5 x 0.20	Unknown	Yes	01		
	H6		NSD						

Lee Poye

Analyst

29-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2A	H7		NSD						
	H8		NSD						
	H9		NSD						
	H10				Damaged				
	I1				Damaged				
	I2		NSD						
	I3				Damaged				
	I4		NSD						
	I5		NSD						
	I6		NSD						
	I7		NSD						
	I8		NSD						
	I9		NSD						
	I10		NSD						
	J1		NSD						
	J2		NSD						
	J3				Damaged				
	J4				Damaged				
	J5		NSD						
	J6		NSD						
	J7		NSD						
	J8				Damaged				
	J9		NSD						
	J10		NSD						
2B									
	A1		NSD						
	A2		NSD						
	A3				Damaged				
	A4				Damaged				
	A5		NSD						
	A6				Damaged				
	A7		NSD						
	A8		NSD						
	A9		NSD						
	A10		NSD						
	B1		NSD						
	B2		NSD						
	B3		NSD						

Lee Poye

Analyst

29-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2B	B4		NSD						
	B5		NSD						
	B6		NSD						
	B7				Damaged				
	B8				Damaged				
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2		NSD						
	C3		NSD						
	C4		NSD						
	C5		NSD						
	C6		NSD						
	C7		NSD						
	C8		NSD						
	C9				Damaged				
	C10		NSD						
	D1		NSD						
	D2		NSD						
	D3		NSD						
	D4		NSD						
	D5		NSD						
	D6		NSD						
	D7		NSD						
	D8		NSD						
	D9		NSD						
	D10				Damaged				
	E1		NSD						
	E2		NSD						
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6		NSD						
	E7		NSD						
	E8		NSD						
	E9		NSD						
	E10		NSD						
	F1		NSD						

Lee Poye

Analyst

29-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2B	F2		NSD						
	F3		NSD						
	F4		NSD						
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9		NSD						
	F10		NSD						
	G1		NSD						
	G2		NSD						
	G3		NSD						
	G4		NSD						
	G5		NSD						
	G6		NSD						
	G7		NSD						
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						
	H4		NSD						
	H5		NSD						
	H6		NSD						
	H7		NSD						
	H8		NSD						
	H9		NSD						
	H10		NSD						
	I1		NSD						
	I2		NSD						
	I3		NSD						
	I4		NSD						
	I5		NSD						
	I6		NSD						
	I7		NSD						
	I8		NSD						
	I9		NSD						

Lee Poye

Analyst

30-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2B	I10		NSD						
	J1		NSD						
	J2		NSD						
	J3				Damaged				
	J4		NSD						
	J5				Damaged				
	J6		NSD						
	J7		NSD						
	J8		NSD						
	J9		NSD						
	J10		NSD						
2C									
	A1		NSD						
	A2		NSD						
	A3		NSD						
	A4		NSD						
	A5				Damaged				
	A6				Damaged				
	A7				Damaged				
	A8		NSD						
	A9		NSD						
	A10		NSD						
	B1		NSD						
	B2		NSD						
	B3		NSD						
	B4		NSD						
	B5		NSD						
	B6		NSD						
	B7				Damaged				
	B8		NSD						
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2		NSD						
	C3		NSD						
	C4		NSD						
	C5		NSD						
	C6		NSD						

Lee Poye

Analyst

30-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2C	C7		NSD						
	C8		NSD						
	C9		NSD						
	C10		NSD						
	D1		NSD						
	D2		NSD						
	D3		NSD						
	D4		NSD						
	D5		NSD						
	D6		NSD						
	D7				Damaged				
	D8				Damaged				
	D9				Damaged				
	D10		NSD						
	E1		NSD						
	E2		NSD						
	E3		NSD						
	E4		NSD						
	E5		NSD						
	E6				Damaged				
	E7		NSD						
	E8		NSD						
	E9		NSD						
	E10		NSD						
	F1		NSD						
	F2		NSD						
	F3		NSD						
	F4		NSD						
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9		NSD						
	F10		NSD						
	G1		NSD						
	G2		NSD						
	G3		NSD						
	G4		NSD						

Lee Poye

Analyst

30-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.
J3 Order #: JH1895372

Sample Number: Gordon Grids
Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (µm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2C	G5		NSD						
	G6		NSD						
	G7		NSD						
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						
	H4		NSD						
	H5				Damaged				
	H6				Damaged				
	H7				Damaged				
	H8				Damaged				
	H9		NSD						
	H10		NSD						
	I1		NSD						
	I2		NSD						
	I3		NSD						
	I4				Damaged				
	I5				Damaged				
	I6				Damaged				
	I7				Damaged				
	I8				Damaged				
	I9				Damaged				
	I10		NSD						
	J1		NSD						
	J2		NSD						
	J3		NSD						
	J4				Damaged				
	J5		NSD						
	J6		NSD						
	J7		NSD						
	J8		NSD						
	J9		NSD						
	J10		NSD						
2D									
	A1		NSD						


 Lee Poye Analyst

31-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μ m)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2D	A2				Damaged				
	A3				Damaged				
	A4		NSD						
	A5		NSD						
	A6		NSD						
	A7		NSD						
	A8		NSD						
	A9		NSD						
	A10		NSD						
	B1		NSD						
	B2		NSD						
	B3		NSD						
	B4		NSD						
	B5		NSD						
	B6		NSD						
	B7		NSD						
	B8		NSD						
	B9		NSD						
	B10		NSD						
	C1		NSD						
	C2		NSD						
	C3		NSD						
	C4		NSD						
	C5		NSD						
	C6		NSD						
	C7		NSD						
	C8		NSD						
	C9		NSD						
	C10		NSD						
	D1		NSD						
	D2		NSD						
	D3		NSD						
	D4		NSD						
	D5		NSD						
	D6		NSD						
	D7		NSD						
	D8		NSD						
	D9		NSD						

Lee Poye

Analyst

31-Jan-2018

Date

Asbestos by TEM - Gordon Grids Lanzo Case**LAB WORKSHEET**

Customer: Joseph D. Satterley, Esq.

J3 Order #: JH1895372

Sample Number: Gordon Grids

Grids: 2A-2D

High Magnification Scan at 15,000X

Grid	G.O. #	Non-Asbestos	Asbestos Tally	L x W (μm)	TYPE	Images			Comments
						EDS	Morphology	SAED	
2D	D10		NSD						
	E1		NSD						
	E2		NSD						
	E3		NSD						
	E4				Damaged				
	E5		NSD						
	E6				Damaged				
	E7		NSD						
	E8		NSD						
	E9		NSD						
	E10		NSD						
	F1				Damaged				
	F2		NSD						
	F3		NSD						
	F4		NSD						
	F5		NSD						
	F6		NSD						
	F7		NSD						
	F8		NSD						
	F9		NSD						
	F10		NSD						
	G1		1	7 x 0.25	Tremolite	Yes	02, 07	03	
	G1		2	2.8 x 0.10	Tremolite	Yes	07		
	G1		3	1.2 x 0.18	Tremolite	Yes	06, 07	05	
	G1	✓	NA	1.2 x 0.20	Tremolite	Yes	07		Cleavage Fragment
	G1		4	1 x 0.05	Tremolite	Yes	07		
	G2		NSD						
	G3		NSD						
	G4		NSD						
	G5		NSD						
	G6		NSD						
	G7		NSD						
	G8		NSD						
	G9		NSD						
	G10		NSD						
	H1		NSD						
	H2		NSD						
	H3		NSD						

Lee Poye

Analyst

31-Jan-2018

Date

Date _____